

The following information offers some guidance in the after care and cleaning of vinyls. In the case of printed graphics, where the graphic has a vinyl Overlamine.

- Allow the vinyl to cure to the substrate for 24-48 hours before cleaning or immersion in water.
- Vinyl may be cleaned with a soft, non-abrasive cleaning cloth, ideally lint free.
- Use warm soapy solution, and rinse after.
- Use Isopropanol to remove stubborn marks, or adhesive.
- Do not use High pressure washers or steam cleaners
- Refer to the data sheets for chemical resistance.
- Do not use abrasive cleaners, abrasive cleaning tools, caustic cleaners or Ketones such as Acetones or MEK.

For further technical support email technical@metamark.co.uk or call +44 (0)1483 571111

Metamark (UK) Limited

Luneside • New Quay Road • Lancaster • LA1 5QP • Tel +44 (0)1524 387140 • Fax +44 (0)1524 387147

Metamark House • Octimum Business Park • Forsyth Road • Woking • GU21 5SF • Tel +44 (0)1483 571111 • Fax +44 (0)1483 570540

sales@metamark.co.uk

www.metamark.co.uk