

### Overlamine has Failed

Problem	Reason	Explanation
Overlamine has tunnelled, cracked, excessive shrinkage, or moved from position on media.	Allow up to 48 hours for solvents to gas off before overlaminating	Excessive solvents from inks will break down the adhesive of the overlamine and cause the overlamine to fail.

For further technical support email [technical@metamark.co.uk](mailto:technical@metamark.co.uk) or call +44 (0)1483 571111

#### Metamark (UK) Limited

Luneside • New Quay Road • Lancaster • LA1 5QP • Tel +44 (0)1524 387140 • Fax +44 (0)1524 387147

Metamark House • Octimum Business Park • Forsyth Road • Woking • GU21 5SF • Tel +44 (0)1483 571111 • Fax +44 (0)1483 570540

[sales@metamark.co.uk](mailto:sales@metamark.co.uk)

[www.metamark.co.uk](http://www.metamark.co.uk)