

The following information offers some guidance in the after care and cleaning of vinyls. In the case of printed graphics, where the graphic has a vinyl Overlaminated.

- Allow the vinyl to cure to the substrate for 24-48 hours before cleaning or immersion in water.
- Vinyl may be cleaned with a soft, non-abrasive cleaning cloth, ideally lint free.
- Use warm soapy solution, and rinse after.
- Use Isopropanol to remove stubborn marks, or adhesive.
- Do not use High pressure washers or steam cleaners
- Refer to the data sheets for chemical resistance.
- Do not use abrasive cleaners, abrasive cleaning tools, caustic cleaners or Ketones such as Acetones or MEK.

---

For further technical support email [technical@metamark.co.uk](mailto:technical@metamark.co.uk) or call +44 (0)1483 571111

### Metamark (UK) Limited

Luneside • New Quay Road • Lancaster • LA1 5QP • Tel +44 (0)1524 387140 • Fax +44 (0)1524 387147  
Metamark House • Genesis Business Park • Albert Drive • Woking • GU21 5RW • Tel +44 (0)1483 571111

[sales@metamark.co.uk](mailto:sales@metamark.co.uk)  
[www.metamark.co.uk](http://www.metamark.co.uk)