

EASY PUFF METALLIC®

SPECIFICATIONS

Composition	Average Thickness	Carrier	Certifications
PU	180 microns	adhesive polyester	REACH n° 1907/2006/EU  

APPLICATION INSTRUCTIONS

APPLIES ON	SUGGESTED CUTTING SETTINGS			TRANSFER SETTINGS			
cotton, polyester, poly/cotton blends not treated with silicon or died with sublimation inks	Blade	Pressure	Speed	Time	Temperature	Pressure	Peel
	45°	100-130 gf	25 cm/sec	5+10 sec	140°C (284°F)	High (5 bar)	cold

- Cut mirrored and peel off excess material
- Place the decoration on the fabric
- Apply for 5 seconds with the recommended parameters, on a professional heat press (do not use a home iron)
- Remove the carrier when it is cold
- Press for another 10 seconds (covered with parchment paper) to create the 3D effect

PRODUCT HIGHLIGHTS

- Easy to cut and weed, thanks to the sticky carrier
- 3D-effect!
- Shiny and metallic finish!

! Depending on the real temperatures of the used heat press and the possible variations of textiles, the final result may slightly vary .
! We recommend to perform a test before launching a production!

CARE AND WASHING RECOMMENDATIONS

Washing	Ironing	Tumble dry	Dry cleaning	Storage Shelf Life	Storage Temperature	Storage Conditions	Position
Hand wash or inside out in cold water	NO	NO	NO	Up to 2 years	Between 18°C and 26°C	Away from sunlight and dust	Vertical

- Wait 24 hours after the application before the first wash
- Respect the textile recommendations
- Do not bleach or use aggressive chemical agents