

PureHT[™]



SPECIFICATIONS

Composition	र्ये Avarage Thickness	Carrier	& Certifications
PU	80-100 microns	Adhesive polyester	REACH n° 1907/2006/EU OEKO-TEX+VEGANOK Certifications pending OEKO-TEX+VEGANOK Certifications pending

APPLICATION INSTRUCTIONS

⊘ Applies on	SUGGESTED CUTTING SETTINGS			TRANSFER SETTINGS			
cotton, polyester, poly/ cotton blends, Elastan (not suited for treated	Blade	<u></u> Pressure	>> Speed	Time	Temperature	Pressure	Peel
and dye sublimated textiles)	45°	60-80 gf	20 cm/sec	15 seconds	135°C (275°F)	medium (2,5/3,5 bar)	hot

- → Cut the material mirrored
- \rightarrow Peel off excess material
- \rightarrow Place the decoration on the garment
- → Apply following the recommended parameters
- → Remove the carrier hot

PRODUCT HIGHLIGHTS

- → COMPOSTABLE PRODUCT (after 180 days in the ground)
- → No environmental impact
- → 100% recyclable carrier
- $oldsymbol{\mathcal{L}}$ NOTE: We highly recommend to perform a test before launching a production.

CARE AND WASHING RECOMMENDATIONS

Washing	Ironing	Tumble dry	Ony cleaning	Storage Shelf Life	Storage Temperature	Storage Conditions	∮ Position
Up to 40°C, inside-out	YES inside-out	YES (cycle: mixed synthetic/ cotton)	No	Up to 2 years	Between 18°C and 26°C	Away from sunlight and dust	Vertical

- ightarrow Wait 24 hours after the application before the first wash
- → Respect the textile recommendations
- → Do not bleach or use aggressive chemical agents